

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING  
PART- 1**

(To be filled by the Head of School/ Institute )

1. Name of the School : GREEN LAND CONVENT SCHOOL
2. Location : CIVIL CITY, NEAR CHANDER NAGAR, LDH.
3. Plot Area : 2000 Sq. Yards
4. Plinth Area : Basement : 6600 Sq. Ft.,  
G.F: 12400 Sq. Ft.,  
1st Floor : 12400 Sq. Ft.,  
2nd Floor: 12400 Sq. Ft.,  
3rd Floor: 12400 Sq. Ft.  
Total Covered Area: 56,200 Sq Ft.
5. Number of Storey's : Basement/ Ground/ First / Second/ Third
6. Year of Construction of Building: : 15 YEARS
7. If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given:
  - a) Name of the Engineer : MR. VED BHUSHAN SHARMA
  - b) Address of Engineer : NEW ABADI, AKALGARH, NEAR AIR FORCE STATION , HALWARA
  - c) Set of Structural drawings used in the construction, if available : ENCLOSED
  - d) Name & address of Architect : MRS. SHELJA GUPTA
8. Whether the building has been constructed for the purpose
  - a) School : YES
  - b) Residential Purpose and converted for use as a School : NO
9. Materials used for roofs
  - a) R.C.C. Slabs/R.B.C. Slabs : R.C.C SLABS
  - b) R.S. Joist & Battons : NO
  - c) Wooden joists & Battons : NO
10. Materials used for walls
  - a) Mud Mortar : NO
  - b) Cement Mortar : YES
  - c) Lime Mortar : NO
11. Flooring
  - a) Conglomerate : YES
  - b) Terrazo : NO
  - c) Brick Paving. : NO
12. A detailed drawing indicating dimensions of the rooms Along with size and location of doors and windows (Attached): ENCLOSED

  
Signature with Stamp of the  
Green Land Convent School  
Principal  
Civil City, Ludhiana.

**PART-II**  
( To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 20/5/2024..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) 31/03/2025.....

*Sukhvir Singh*  
Sub Divisional Engineer  
Provincial Division No. 3,  
P. W. D. B & R Br., Ludhiana.

*Sukhvir Singh*  
Sub Divisional Engineer,



# ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

Phone/Fax No. 0161-2420082

Email-ID :- cepdlldnpwdpb@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ  
ਗਰੀਨ ਲੈਂਡ ਕੋਨਵੈਂਟ ਸਕੂਲ  
ਬਿਸ਼ਨ ਇੰਨਕਲੇਵ, ਸਿਵਲ ਸਿਟੀ,  
ਚੰਦਰ ਨਗਰ, ਲੁਧਿਆਣਾ।

ਨੰ. ੧੫੨

ਮਿਤੀ: ੦੫/੦੭/੨੦੨੪

ਵਿਸ਼ਾ:- Regarding issuance of Building Safety Certificate (2024-2025)

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ. GLCS/CC/LDH/2024-25/02 ਮਿਤੀ 25/04/2024

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਤੇ ਹਵਾਲੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਗਰੀਨ ਲੈਂਡ ਕੋਨਵੈਂਟ ਸਕੂਲ, ਬਿਸ਼ਨ ਇੰਨਕਲੇਵ, ਸਿਵਲ ਸਿਟੀ, ਚੰਦਰ ਨਗਰ, ਲੁਧਿਆਣਾ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ ਮੁਤਾਬਕ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮਿਤੀ 31/03/2025 ਤੱਕ ਸਹੀ ਜਾਪਦੀ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਇਸ ਦਫਤਰ ਦੀ ਮੰਨਜੂਰੀ ਤੋਂ ਬਗੈਰ ਕੋਈ ਵੀ ਐਡੀਸ਼ਨਲ ਅਲਟਰੇਸ਼ਨ ਨਾ ਕੀਤੀ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,  
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ. 186 ਮਿਤੀ 24/06/2024 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਅਗਲੀ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,  
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।